


**Contact:**

Telefon: 0733 513 353 / 0721 442 354

Fix/fax: 0318 057 812

Email: [turboparts.sa@gmail.com](mailto:turboparts.sa@gmail.com)

Website: [www.turbomaster.ro](http://www.turbomaster.ro)

**Avantajele reconditionarii unei turbosuflante:**

- avand in vedere ca in procesul de reconditionare al turbosuflantei se inlocuieste toata partea functionala, in mod automat obtineti un pret mai avantajos decat in cazul achizitionarii unei turbosuflante noi cu aceleasi caracteristici de functionare
- beneficiati de un certificat de garantie pentru 12 luni fara limita de km, la fel ca si in cazul turbosuflantelor noi pe original

**Preturi:**

- reparatie turbosuflante Garrett, incepand de la 119 €
- reparatie turbosuflante KKK, incepand de la 139 €
- reparatie turbosuflante IHI, Toyota, Mitsubishi, incepand de la 159 €
- reparatie turbosuflante de utilaje, incepand de la 179 €
- kituri de reparatie, incepand de la 50 €

Pentru clientii din afara Bucurestiului, cu ajutorul firmelor de curierat rapid, oferim posibilitatea de a trimite turbosuflanta la sediul nostru in 24 ore.

Clientii care doresc sa se ocupe singuri de reparatia turbosuflantei pot achizitiona de la noi urmatoarele piese: [cartridge \(chra\) turbo](#), kit de reparatie turbo, ax turbo, compresor turbo, corp turbo, supapa de vacum turbo.

Puteti vizita [magazinul](#) nostru pentru a comanda online sau ne puteti apela la numerele de telefon aflate in pagina de [contact](#).

**Ce oferim?**

- servicii calitative oferite de atelierul nostru pentru reparatii turbosuflante
- echilibrare de tip VSR, 250.000 rotatii/minut
- piese de schimb originale pentru o functionare durabila
- turbosuflante reconditionate la preturi avantajoase
- servicii de calitate si certificate de echilibrare
- distribuim si reparam turbosuflante Garrett, KK, Mitsubishi, Holset, Schwitzer la nivel local si national

## Oferta cartridge (CHRA) Turbo

Luna aceasta sunt propuse spre vanzare urmatoarele turbosufiante pentru VW, Audi, Seat, Skoda, Ford, BMW, Peugeot, Renault cu urmatoarele coduri:

2247297F, 2247297G, 2247297H, 2247901H, 2247905H, 2248901G, 2248905G, 11652247297F, 11652247297G, 11652247297H, 11652247901H, 11652247905H, 11652248901G, 11652248905G, 2247901104, 7787626F, 7787626G, 7787628G, 7794144D, 7794144SD, 11657794144, 11657787626F, 11657787626G, 11657787628G, 11657794144D, 11657794144SD, 7794144, 77876260, 116577876260, 2248906G, 2248906H, 22489069, 2247691F, 2247691G, 2247691H

2248906I08, 2248907H, 11652248906G, 11652248906H, 116522489069, 11652247691F, 11652247691G, 11652247691H, 11652248907H, 074145703E, 070145701H, 070145702A, 070145701K, 070145701E, 05, 9145701C, 059145701G, 059145702D, 059145701E, 059145701D, 059145701F, 059145701S, 058145703L, 058145703H, 058145703L, 058145703J – 058145703N, 03G253019A, 03G253014H, 03G253010J, 5439 988 0022, 038253016K, 03G253014F, 038253014G, 038253016R, 038253010D, 038253056E, 038253056G, 038253010P + 038253016K

03G253014F, 751851-3, 038253019C, 03G253016N, 5439 988 0017, 038253019N, 03G253014E, 038253016L, 038253014A, 038253010G, 038253056A, 038253010A, 038253010S + 038253019C + 038253019N, 028145702H, 038145702E, 038145702E, 038145702G, 038145702, 03814570, 028145702H, 028145702R, 038145702L, 074145701D

038253016G, 03G253016R, 90529201007104, 062145701A, 03G253019N, 03G253014K, 03G253010A, 03G257019, 454192-5005S, 700447-5008S, 750431-5012S, 454191-5015S, 454192-5005S, 720931-5004S, 5304 988 0032, 454135-5009S, 454135-5010S, 5303 988 0005, 5303 988 0029, 724930-5009S, 751851-5003S, 5439 988 0022, 713672-5006S, 713673-5006S, 5439 988 0017, 717858-5008S, 454231-5007S, 454231-5010S, 454205-5006S, 721021-5006S, 721204-5001S, 757042-5015S

8200106870 – 7701475282, 8200110519, 8200110519A, 8200381645, 8200369581, 7711135749, 7701474960, 7701477263, 7711368748, 8200683855, 8200544912, 7700108052, 8200348244, 8200458162, 7701472228, 8200683854, 7711134299, 8200544911, 7711497142, 8200204572 – 8200578315 – 8200360800 – 7701476183, 8200405203, 8200507856, 8200625683, 8200578381, 7701476883, 8200100284, 8200459493, 8200459493A, 7711134972 7701473756, 8200683861, 9640254880 – 9640668680 – 9631421480 – 9662465380 – 0375F8 – 9840668680, 9650764480, 965183988  
0, 1479055, 9657571880 0375J6

9656125880, 9663199280, 9657248680, 9657531880, XS4Q6K682DC – XS4Q6K682DB – 1094575 – 1351395, XS4Q6K682DE – XS4Q6K682DF, 2S7Q6K682AG, 2S7Q6K682AC, 2S7Q6K682AE, 1219649, 2S7Q6K682AF, 2S7Q6K682AD, 3S7Q6K682AE, 1383646, 3S7Q6K682AF, 3S7Q6K682AD, 1435150, 2S7Q6K682AJ, 1132648, 1202122, 1256751, 1S7Q6K682BH – 1126058 – 1201315, 1S7Q6K682AF, 1S7Q6K682AD, 1S7Q6K682AG, 1S7Q6K682AK, 1S7Q6K682AE, 1S7Q6K682AJ, 1404041, 4S7Q6K682EL, 4S7Q6K682EH, 4S7Q6K682EK, 4S7Q6K682EF, 1435151, 4S7Q6K682EN

1S4Q6K682AL, 1S4Q6K682AK, 1S4Q6K682AH, 1212579, 1S4Q6K682AJ, 1S4Q6K682AF, 1S4Q6K682AG, 1222163, 1S4Q6K682AS, 1S4Q6K682AD, 1S4Q6K682AE, 1210912 1257260, 1349413, 1351396, 1520781, 1203083, 1207990 1S4Q6K682AP, 718089-5008S, 708639-5010S, 751768-5004S 5439 998 0027, 5439 998 0070, 720244-5004S, 726683-5002S, 753420-5005S, 706499-5004S, 714467-5014S, 704226-5007S, 708618-5011S, 728680-5015S, 713517-5016S



Alba  
 Arad  
 Arges  
 Bacau  
 Bihor  
 Bistrita-Nasaud  
 Botosani  
 Braila  
 Brasov  
 Bucuresti  
 Buzau  
 Calarasi  
 Caras-Severin  
 Cluj  
 Constanta  
 Covasna  
 Dambovita  
 Dolj  
 Galati  
 Giurgiu  
 Gorj

Harghita  
 Hunedoara  
 Ialomita  
 Iasi  
 Ilfov  
 Maramures  
 Mehedinti  
 Mures  
 Neamt  
 Olt  
 Prahova  
 Salaj  
 Satu Mare  
 Sibiu  
 Suceava  
 Teleorman  
 Timis  
 Tulcea  
 Vaslui  
 Valcea  
 Vrancea

Reconditionam turbosuflyante la nivel national